



Acer Travelmate 220 RAM Replacement

Replacement of RAM chips

Written By: Kevin A



INTRODUCTION

These are common symptoms requiring the replacement of the RAM chips in an Acer Travelmate 220 include:

1. The inability to turn your computer on.
2. Your computer randomly crashing/turning off.
3. Your computer randomly rebooting/turning on.
4. The inability to install new programs to your computer.



TOOLS:

- [Phillips #00 Screwdriver](#) (1)
- [iFixit Opening Tools](#) (1)



PARTS:



- [PC100 128 MB RAM Chip](#) (1)
-

Step 1 — RAM Chip





- Place the computer with the bottom facing up.

Step 2



- Locate the larger cover panel in the upper left hand corner of the computer.
- Locate the Phillips screw holding the large cover panel in place.

Step 3





- Remove the located screw with the Phillips #00 screwdriver.

Step 4



- Slide the large cover panel to the right, until you hear a click.

Step 5



- Place the plastic opening tool in the gap created to the left of the large cover panel.
- Pry the cover panel up and remove it from the computer.

Step 6



- Locate the white plastic levers on each side of the two RAM chips.

Step 7



- Locate the first RAM chip.
- Push the plastic levers away from the first RAM chip.

Step 8



- Lift the RAM chip from the compartment.
- Repeat steps 7 and 8 to replace the second RAM chip.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-17 10:22:35 PM.